

Sample	Symbol	Elev. (ft)	USCS	% Fines	% Organics	% Carbonates	Median	Mean	Skew	Kurt	Sort
BC06-59 #16.0	—●—	-34.0	SP	#200 - 1.39 #230 - 1.37		0.42	1.86	1.87	-0.01	4.81	0.46

Comments:

Depths and elevations based on measured values

Scientific Environmental Applications
5575 Willoughby Drive
Melbourne, FL 32934
ph 321 254-2708
fax 321 254-2708

Sample Information	
Project Name:	Baldwin County, AL 2006
Analysis Date:	07-29-06
Analyzed By:	SEA Inc.
Easting (X, ft):	1,796,181
Northing (Y, ft):	61,378
Horizontal System:	NAD 1983
Vertical System:	NAVD 88