

PERCENT FINER



SIEVE SIZE	PERCENT FINER	SPEC.* PERCENT	PASS? (X=NO)
.375	100.0		
#4	100.0		
#10	99.9		
#20	98.7		
#40	70.3		
#60	18.7		
#100	8.3		
#200	6.1		

L-100