


Gravel		Sand			Silt and Clay
Coarse	Fine	Coarse	Medium	Fine	

Sample	Symbol	Elev. (ft)	USCS	% Fines	% Organics	% Carbonates	Median	Mean	Skew	Kurt	Sort	Sample Information	
DIVC-22-01 #7	—●—	-33.9	SP-SM	#200 - 7.86 #230 - 7.80		4	2.41	2.32	-2.38	14.92	0.56	Project Name:	Dauphin Island Supplemental Investigation
Comments:												Analysis Date:	01-24-22
Depths and elevations based on measured values												Analyzed By:	SD
							APTIM 6401 Congress Avenue, Suite 140 Boca Raton, FL 33487 ph (561) 391-8102					Easting (X, ft):	1,788,970
												Northing (Y, ft):	63,972
												Horizontal Datum:	NAD 1983
												Vertical Datum:	NAVD 88