



UPDATED_COMPOSITES.GPJ 2/16/22



Gravel		Sand			Silt and Clay
Coarse	Fine	Coarse	Medium	Fine	

Sample	Symbol	Elev. (ft)	USCS	% Fines	% Organics	% Carbonates	Median	Mean	Skew	Kurt	Sort	Sample Information	
DIVC-22-01 COMP.	—●—	0.0	SP	#200 - 1.47 #230 - 1.45			2.11	2.06	-1.55	10.36	0.68	Project Name:	Dauphin Island Shore Protection
Comments:												Analysis Date:	02-09-22
Depths and elevations based on measured values												Analyzed By:	BF
						APTIM 6401 Congress Avenue, Suite 140 Boca Raton, FL 33487 ph (561) 391-8102						Easting (X, ft):	
												Northing (Y, ft):	
												Horizontal Datum:	NAD 1983
												Vertical Datum:	NAVD 88