


Gravel		Sand			Silt and Clay
Coarse	Fine	Coarse	Medium	Fine	

Sample	Symbol	Elev. (ft)	USCS	% Fines	% Organics	% Carbonates	Median	Mean	Skew	Kurt	Sort	Sample Information	
DIVC-22-03 #6	—●—	-28.9	SW	#200 - 1.55 #230 - 1.53		10	1.54	1.38	-1.82	8.32	0.86	Project Name:	Dauphin Island Supplemental Investigation
Comments:												Analysis Date:	01-25-22
Depths and elevations based on measured values												Analyzed By:	SF
						APTIM 6401 Congress Avenue, Suite 140 Boca Raton, FL 33487 ph (561) 391-8102						Easting (X, ft):	1,789,468
												Northing (Y, ft):	64,747
												Horizontal Datum:	NAD 1983
												Vertical Datum:	NAVD 88