


Boring Designation BI-PB-008-10

DRILLING LOG		DIVISION South Atlantic		INSTALLATION Mobile District		SHEET 1 OF 1 SHEETS	
1. PROJECT MsCIP Barrier Island Restoration Petit Bois Pass- AL East				9. SIZE AND TYPE OF BIT N/A			
2. BORING DESIGNATION BI-PB-008-10		LOCATION COORDINATES E = 1,140,592 N = 254,350		10. COORDINATE SYSTEM/DATUM State Plane, MSE (U.S. Ft.)		HORIZONTAL NAD83 VERTICAL NAVD88	
3. DRILLING AGENCY Corps of Engineers - CESAM		CONTRACTOR FILE NO.		11. MANUFACTURER'S DESIGNATION OF DRILL Vibrocure		<input type="checkbox"/> AUTO HAMMER <input type="checkbox"/> MANUAL HAMMER	
4. NAME OF DRILLER Construction Solutions International, Inc.				12. TOTAL SAMPLES 3		DISTURBED 0 UNDISTURBED (UD) 0	
5. DIRECTION OF BORING <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED		DEG. FROM VERTICAL		13. TOTAL NUMBER CORE BOXES			
		BEARING		14. WATER DEPTH 33 Ft.			
6. THICKNESS OF OVERBURDEN N/A				15. DATE BORING 06-26-10		STARTED 06-26-10 COMPLETED 06-26-10	
7. DEPTH DRILLED INTO ROCK N/A				16. ELEVATION TOP OF BORING -31.5 Ft.			
8. TOTAL DEPTH OF BORING 16.9 Ft.				17. TOTAL RECOVERY FOR BORING 100%			
				18. SIGNATURE AND TITLE OF INSPECTOR Marty Gates, Geologist			
ELEV.	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS	SAMPLE	LABORATORY RESULTS		
-31.5	0.0						
			SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace silt, lt. gray (SP)	A	Classification: SP Color: 2.5Y 8/1-white D50: 0.3816 mm % Fines: 1.7		
				B	Classification: SP Color: 2.5Y 8/1-white D50: 0.397 mm % Fines: 1.7		
				C	Classification: SP Color: 2.5Y 6/2-light brownish gray D50: 0.3718 mm % Fines: 4.3		
-48.4	16.9						
			NOTES: 1. Soils are field visually classified in accordance with the Unified Soils Classification System. 2. NS = Sample not submitted for laboratory analysis from this interval. 3. Seafloor elevation calculated using sampling vessel's fathometer water depth reading and applying NOAA tidal gauge data conversion factor.				