


# Boring Designation BI-PB-014-10

DRILLING LOG		DIVISION South Atlantic		INSTALLATION Mobile District		SHEET 1 OF 1 SHEETS	
1. PROJECT MsCIP Barrier Island Restoration Petit Bois Pass- AL East				9. SIZE AND TYPE OF BIT N/A			
2. BORING DESIGNATION BI-PB-014-10		LOCATION COORDINATES E = 1,149,377 N = 253,637		10. COORDINATE SYSTEM/DATUM State Plane, MSE (U.S. Ft.)		HORIZONTAL NAD83 VERTICAL NAVD88	
3. DRILLING AGENCY Corps of Engineers - CESAM		CONTRACTOR FILE NO.		11. MANUFACTURER'S DESIGNATION OF DRILL Vibrocure		<input type="checkbox"/> AUTO HAMMER <input type="checkbox"/> MANUAL HAMMER	
4. NAME OF DRILLER Construction Solutions International, Inc.				12. TOTAL SAMPLES 3		DISTURBED 0 UNDISTURBED (UD)	
5. DIRECTION OF BORING <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED		DEG. FROM VERTICAL		13. TOTAL NUMBER CORE BOXES			
		BEARING		14. WATER DEPTH 38 Ft.			
6. THICKNESS OF OVERBURDEN N/A				15. DATE BORING 06-26-10		STARTED 06-26-10 COMPLETED 06-26-10	
7. DEPTH DRILLED INTO ROCK N/A				16. ELEVATION TOP OF BORING -36.8 Ft.			
8. TOTAL DEPTH OF BORING 17.4 Ft.				17. TOTAL RECOVERY FOR BORING 100%			
				18. SIGNATURE AND TITLE OF INSPECTOR Marty Gates, Geologist			
ELEV.	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS	SAMPLE	LABORATORY RESULTS		
-36.8	0.0						
			SAND, poorly-graded, mostly medium-grained sand-sized quartz, trace silt, trace shell fragments, lt. gray (SP)	A	Classification: SP Color: 2.5Y 7/2-light gray D50: 0.3521 mm % Fines: 3.5		
				B	Classification: SP Color: 2.5Y 8/1-white D50: 0.371 mm % Fines: 2.7		
				C	Classification: SP Color: 2.5Y 7/1-light gray D50: 0.3535 mm % Fines: 4.6		
-54.2	17.4						
			NOTES: 1. Soils are field visually classified in accordance with the Unified Soils Classification System. 2. NS = Sample not submitted for laboratory analysis from this interval. 3. Seafloor elevation determined from 2010 USACE survey.				