

# Boring Designation BI-PB-046-10

DRILLING LOG		DIVISION South Atlantic		INSTALLATION Mobile District		SHEET 1 OF 2 SHEETS	
1. PROJECT MsCIP Barrier Island Restoration Petit Bois Pass- AL West				9. SIZE AND TYPE OF BIT N/A			
2. BORING DESIGNATION BI-PB-046-10		LOCATION COORDINATES E = 1,137,591 N = 251,286		10. COORDINATE SYSTEM/DATUM State Plane, MSE (U.S. Ft.)		HORIZONTAL NAD83	
3. DRILLING AGENCY Corps of Engineers - CESAM		CONTRACTOR FILE NO.		11. MANUFACTURER'S DESIGNATION OF DRILL Vibrocure		<input type="checkbox"/> AUTO HAMMER <input type="checkbox"/> MANUAL HAMMER	
4. NAME OF DRILLER Construction Solutions International, Inc.				12. TOTAL SAMPLES		DISTURBED 0	
5. DIRECTION OF BORING <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED				13. TOTAL NUMBER CORE BOXES		14. WATER DEPTH 37 Ft.	
6. THICKNESS OF OVERBURDEN N/A				15. DATE BORING		STARTED 08-06-10	
7. DEPTH DRILLED INTO ROCK N/A				16. ELEVATION TOP OF BORING -35.8 Ft.		COMPLETED 08-06-10	
8. TOTAL DEPTH OF BORING 20.0 Ft.				17. TOTAL RECOVERY FOR BORING 100%		18. SIGNATURE AND TITLE OF INSPECTOR Chris Gillentine, Geologist	
ELEV.	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS	SAMPLE	LABORATORY RESULTS		
-35.8	0.0		CLAY, fat, dark gray (CH)	NS			
-41.8	6.0		SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, dark gray (SP)				
-44.8	9.0		CLAY, fat, dark gray (CH)				
-55.8	20.0		NOTES: 1. Soils are field visually classified in accordance with the Unified Soils Classification System. 2. NS = Sample not submitted for laboratory analysis from this interval. 3. Seafloor elevation calculated using sampling				

<b>DRILLING LOG (Cont. Sheet)</b>			<b>INSTALLATION</b> Mobile District		<b>SHEET 2</b> <b>OF 2 SHEETS</b>
<b>PROJECT</b> MsCIP Barrier Island Restoration			<b>COORDINATE SYSTEM/DATUM</b> State Plane, MSE (U.S. Ft.)	<b>HORIZONTAL</b> NAD83	<b>VERTICAL</b> NAVD88
<b>LOCATION COORDINATES</b> X = 1,137,591 Y = 251,286			<b>ELEVATION TOP OF BORING</b> -35.8 Ft.		
<b>ELEV.</b>	<b>DEPTH</b>	<b>LEGEND</b>	<b>CLASSIFICATION OF MATERIALS</b>	<b>SAMPLE</b>	<b>LABORATORY RESULTS</b>
			vessel's fathometer water depth reading and applying NOAA tidal gauge data conversion factor.		