

# Boring Designation BI-PB-106-10

DRILLING LOG		DIVISION South Atlantic		INSTALLATION Mobile District		SHEET 1 OF 1 SHEETS	
1. PROJECT Barrier Island Restoration Petit Bois				9. SIZE AND TYPE OF BIT N/A			
2. BORING DESIGNATION BI-PB-106-10		LOCATION COORDINATES E = 1,133,338 N = 251,293		10. COORDINATE SYSTEM/DATUM State Plane, MSE (U.S. Ft.)		HORIZONTAL NAD83	
3. DRILLING AGENCY Corps of Engineers - CESAM		CONTRACTOR FILE NO.		11. MANUFACTURER'S DESIGNATION OF DRILL Vibrocure		<input type="checkbox"/> AUTO HAMMER <input type="checkbox"/> MANUAL HAMMER	
4. NAME OF DRILLER Construction Solutions International, Inc.				12. TOTAL SAMPLES 2		DISTURBED 0	
5. DIRECTION OF BORING <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED				13. TOTAL NUMBER CORE BOXES		14. WATER DEPTH 33 Ft.	
6. THICKNESS OF OVERBURDEN N/A				15. DATE BORING 08-04-10		STARTED 08-04-10	
7. DEPTH DRILLED INTO ROCK N/A				16. ELEVATION TOP OF BORING -33.5 Ft.		COMPLETED 08-04-10	
8. TOTAL DEPTH OF BORING 9.5 Ft.				17. TOTAL RECOVERY FOR BORING 100%		18. SIGNATURE AND TITLE OF INSPECTOR Chris Gillentine, Geologist	
ELEV.	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS	SAMPLE	LABORATORY RESULTS		
-33.5	0.0						
-35.5	2.0		CLAY, fat, dark gray (CH)	A	Classification: SP-SM Color: 2.5Y 4/2-dark grayish brown D50: 0.2503 mm % Fines: 9.2		
-43.0	9.5		SAND, poorly-graded, mostly medium-grained sand-sized quartz, dark brown (SP) At El. -37.5 Ft., trace silt, gray	B	Classification: SM Color: 5Y 5/2-olive gray D50: 0.2584 mm % Fines: 19.3		
NOTES: 1. Soils are field visually classified in accordance with the Unified Soils Classification System. 2. NS = Sample not submitted for laboratory analysis from this interval. 3. Seafloor elevation calculated using sampling vessel's fathometer water depth reading and applying NOAA tidal gauge data conversion factor.							

# Boring Designation BI-PB-106-10

DRILLING LOG		DIVISION South Atlantic		INSTALLATION Mobile District		SHEET 1 OF 1 SHEETS	
1. PROJECT MsCIP Barrier Island Restoration Petit Bois Pass- AL West				9. SIZE AND TYPE OF BIT N/A			
2. BORING DESIGNATION BI-PB-106-10		LOCATION COORDINATES E = 1,133,338 N = 251,293		10. COORDINATE SYSTEM/DATUM State Plane, MSE (U.S. Ft.)		HORIZONTAL NAD83 VERTICAL NAVD88	
3. DRILLING AGENCY Corps of Engineers - CESAM		CONTRACTOR FILE NO.		11. MANUFACTURER'S DESIGNATION OF DRILL Vibracore		<input type="checkbox"/> AUTO HAMMER <input type="checkbox"/> MANUAL HAMMER	
4. NAME OF DRILLER Construction Solutions International, Inc.				12. TOTAL SAMPLES 2		DISTURBED 0 UNDISTURBED (UD)	
5. DIRECTION OF BORING <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED		DEG. FROM VERTICAL		13. TOTAL NUMBER CORE BOXES			
		BEARING		14. WATER DEPTH 33 Ft.			
6. THICKNESS OF OVERBURDEN N/A				15. DATE BORING 08-04-10		STARTED 08-04-10 COMPLETED 08-04-10	
7. DEPTH DRILLED INTO ROCK N/A				16. ELEVATION TOP OF BORING -33.5 Ft.			
8. TOTAL DEPTH OF BORING 9.5 Ft.				17. TOTAL RECOVERY FOR BORING 100%			
				18. SIGNATURE AND TITLE OF INSPECTOR Chris Gillentine, Geologist			
ELEV.	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS	SAMPLE	LABORATORY RESULTS		
-33.5	0.0						
-35.5	2.0		CLAY, fat, dark gray (CH)	A	Classification: SP-SM Color: 2.5Y 4/2-dark grayish brown D50: 0.2503 mm % Fines: 9.2		
			SAND, poorly-graded, mostly medium-grained sand-sized quartz, dark brown (SP) At El. -37.5 Ft., trace silt, gray				
-43.0	9.5			B	Classification: SM Color: 5Y 5/2-olive gray D50: 0.2584 mm % Fines: 19.3		
			NOTES: 1. Soils are field visually classified in accordance with the Unified Soils Classification System. 2. NS = Sample not submitted for laboratory analysis from this interval. 3. Seafloor elevation calculated using sampling vessel's fathometer water depth reading and applying NOAA tidal gauge data conversion factor.				