

Boring Designation BI-PB-116-10

DRILLING LOG		DIVISION South Atlantic		INSTALLATION Mobile District		SHEET 1 OF 1 SHEETS	
1. PROJECT MsCIP Barrier Island Restoration Petit Bois Pass- AL East				9. SIZE AND TYPE OF BIT N/A			
2. BORING DESIGNATION BI-PB-116-10		LOCATION COORDINATES E = 1,142,156 N = 257,056		10. COORDINATE SYSTEM/DATUM State Plane, MSE (U.S. Ft.)		HORIZONTAL NAD83	
3. DRILLING AGENCY Corps of Engineers - CESAM		CONTRACTOR FILE NO.		11. MANUFACTURER'S DESIGNATION OF DRILL Vibrocure		<input type="checkbox"/> AUTO HAMMER <input type="checkbox"/> MANUAL HAMMER	
4. NAME OF DRILLER Construction Solutions International, Inc.				12. TOTAL SAMPLES 2		DISTURBED 0	
5. DIRECTION OF BORING <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED				13. TOTAL NUMBER CORE BOXES		14. WATER DEPTH 16 Ft.	
6. THICKNESS OF OVERBURDEN N/A				15. DATE BORING 07-29-10		STARTED 07-29-10	
7. DEPTH DRILLED INTO ROCK N/A				16. ELEVATION TOP OF BORING -15.6 Ft.		COMPLETED 07-29-10	
8. TOTAL DEPTH OF BORING 15.0 Ft.				17. TOTAL RECOVERY FOR BORING 100%		18. SIGNATURE AND TITLE OF INSPECTOR Chris Gillentine, Geologist	
ELEV.	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS	SAMPLE	LABORATORY RESULTS		
-15.6	0.0						
			SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace shell fragments, gray (SP)	A	Classification: SP Color: 2.5Y 6/2-light brownish gray D50: 0.3445 mm % Fines: 2.7		
				B	Classification: SP Color: 2.5Y 7/1-light gray D50: 0.2828 mm % Fines: 4.6		
-22.6	7.0						
			CLAY, fat, dark gray (CH)	NS			
-30.6	15.0						
NOTES:							
1. Soils are field visually classified in accordance with the Unified Soils Classification System.							
2. NS = Sample not submitted for laboratory analysis from this interval.							
3. Seafloor elevation calculated using sampling vessel's fathometer water depth reading and applying NOAA tidal gauge data conversion factor.							