

Boring Designation BI-PB-126-10

DRILLING LOG		DIVISION South Atlantic		INSTALLATION Mobile District		SHEET 1 OF 1 SHEETS	
1. PROJECT MsCIP Barrier Island Restoration Petit Bois Pass- AL East				9. SIZE AND TYPE OF BIT N/A			
2. BORING DESIGNATION BI-PB-126-10		LOCATION COORDINATES E = 1,154,059 N = 254,378		10. COORDINATE SYSTEM/DATUM State Plane, MSE (U.S. Ft.)		HORIZONTAL NAD83 VERTICAL NAVD88	
3. DRILLING AGENCY Corps of Engineers - CESAM		CONTRACTOR FILE NO.		11. MANUFACTURER'S DESIGNATION OF DRILL Vibracore		<input type="checkbox"/> AUTO HAMMER <input type="checkbox"/> MANUAL HAMMER	
4. NAME OF DRILLER Construction Solutions International, Inc.				12. TOTAL SAMPLES 3		DISTURBED 3 UNDISTURBED (UD) 0	
5. DIRECTION OF BORING <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED		DEG. FROM VERTICAL		13. TOTAL NUMBER CORE BOXES			
		BEARING		14. WATER DEPTH 36 Ft.			
6. THICKNESS OF OVERBURDEN N/A				15. DATE BORING 08-07-10		STARTED 08-07-10 COMPLETED 08-07-10	
7. DEPTH DRILLED INTO ROCK N/A				16. ELEVATION TOP OF BORING -36.1 Ft.			
8. TOTAL DEPTH OF BORING 14.7 Ft.				17. TOTAL RECOVERY FOR BORING 100%			
				18. SIGNATURE AND TITLE OF INSPECTOR Chris Gillentine, Geologist			
ELEV.	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS	SAMPLE	LABORATORY RESULTS		
-36.1	0.0						
			SAND, poorly-graded, mostly fine to medium-grained sand-sized quartz, trace shell fragments, trace silt, lt. gray (SP)	A	Classification: SP-SM Color: 2.5Y 5/2-grayish brown D50: 0.3272 mm % Fines: 9.1		
				B	Classification: SP-SM Color: 2.5Y 5/1-gray D50: 0.3205 mm % Fines: 6.2		
				C	Classification: SP-SM Color: 2.5Y 5/1-gray D50: 0.3173 mm % Fines: 11		
-50.8	14.7						
			NOTES: 1. Soils are field visually classified in accordance with the Unified Soils Classification System. 2. NS = Sample not submitted for laboratory analysis from this interval. 3. Seafloor elevation determined from 2010 USACE survey.				