

Boring Designation BI-PB-131-11

DRILLING LOG		DIVISION South Atlantic		INSTALLATION Mobile District		SHEET 1 OF 1 SHEETS	
1. PROJECT MsCIP Barrier Island Restoration Petit Bois Pass- AL West				9. SIZE AND TYPE OF BIT N/A			
2. BORING DESIGNATION BI-PB-131-11		LOCATION COORDINATES E = 1,131,148 N = 253,747		10. COORDINATE SYSTEM/DATUM State Plane, MSE (U.S. Ft.)		HORIZONTAL NAD83	
3. DRILLING AGENCY Corps of Engineers - CESAM		CONTRACTOR FILE NO.		11. MANUFACTURER'S DESIGNATION OF DRILL Vibracore		<input type="checkbox"/> AUTO HAMMER <input type="checkbox"/> MANUAL HAMMER	
4. NAME OF DRILLER Construction Solutions International, Inc.				12. TOTAL SAMPLES 2		DISTURBED 0	
5. DIRECTION OF BORING <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED				13. TOTAL NUMBER CORE BOXES		14. WATER DEPTH 28.5 Ft.	
6. THICKNESS OF OVERBURDEN N/A				15. DATE BORING 06-30-11		STARTED 06-30-11	
7. DEPTH DRILLED INTO ROCK N/A				16. ELEVATION TOP OF BORING -26.8 Ft.		COMPLETED 06-30-11	
8. TOTAL DEPTH OF BORING 14.3 Ft.				17. TOTAL RECOVERY FOR BORING 100%			
				18. SIGNATURE AND TITLE OF INSPECTOR Michele Johnson, Geologist			
ELEV.	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS	SAMPLE	LABORATORY RESULTS		
-26.8	0.0						
			SAND, poorly-graded, trace shell fragments, lt. gray (SP)	A	Classification: SP-SM Color: 5Y 7/1-light gray D50: 0.3095 mm % Fines: 6.5		
-30.1	3.3						
			SAND, poorly-graded with silt, trace shell fragments, gray (SP-SM)	B	Classification: SP-SM Color: 2.5Y 6/2-light brownish gray D50: 0.2957 mm % Fines: 7.2		
				NS			
-41.1	14.3						
			NOTES: 1. Soils are field visually classified in accordance with the Unified Soils Classification System. 2. NS = Sample not submitted for laboratory analysis from this interval. 3. Seafloor elevation determined from 2010 USACE survey.				