

Boring Designation BI-PB-145-11

DRILLING LOG		DIVISION South Atlantic		INSTALLATION Mobile District		SHEET 1 OF 1 SHEETS	
1. PROJECT MsCIP Barrier Island Restoration Petit Bois Pass- AL East				9. SIZE AND TYPE OF BIT N/A			
2. BORING DESIGNATION BI-PB-145-11		LOCATION COORDINATES E = 1,155,559 N = 257,212		10. COORDINATE SYSTEM/DATUM State Plane, MSE (U.S. Ft.)		HORIZONTAL NAD83	
3. DRILLING AGENCY Corps of Engineers - CESAM		CONTRACTOR FILE NO.		11. MANUFACTURER'S DESIGNATION OF DRILL Vibracore		<input type="checkbox"/> AUTO HAMMER <input type="checkbox"/> MANUAL HAMMER	
4. NAME OF DRILLER Construction Solutions International, Inc.				12. TOTAL SAMPLES 3		UNDISTURBED (UD) 0	
5. DIRECTION OF BORING <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED		DEG. FROM VERTICAL		13. TOTAL NUMBER CORE BOXES			
		BEARING		14. WATER DEPTH 36.6 Ft.			
6. THICKNESS OF OVERBURDEN N/A				15. DATE BORING 07-01-11		COMPLETED 07-01-11	
7. DEPTH DRILLED INTO ROCK N/A				16. ELEVATION TOP OF BORING -34.5 Ft.			
8. TOTAL DEPTH OF BORING 16.4 Ft.				17. TOTAL RECOVERY FOR BORING 100%			
				18. SIGNATURE AND TITLE OF INSPECTOR Michele Johnson, Geologist			
ELEV.	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS	SAMPLE	LABORATORY RESULTS		
-34.5	0.0						
			SAND, poorly-graded, mostly medium-grained sand-sized quartz, gray (SP)	A	Classification: SP Color: - D50: 0.3263 mm % Fines: 4.1		
-38.5	4.0			B	Classification: SP Color: 5Y 7/1-light gray D50: 0.3541 mm % Fines: 2.9		
			SAND, clayey, trace shell fragments, clayey, gray (SC)	C	Classification: SM Color: 2.5Y 5/1-gray D50: 0.189 mm % Fines: 21.2		
-41.8	7.3			NS			
					NOTES: 1. Soils are field visually classified in accordance with the Unified Soils Classification System. 2. NS = Sample not submitted for laboratory analysis from this interval. 3. Seafloor elevation calculated using sampling vessel's fathometer water depth reading and applying NOAA tidal gauge data conversion factor.		
-50.9	16.4						