




DEPARTMENT OF THE ARMY, SAVANNAH DISTRICT, ENVIRONMENTAL AND MATERIALS UNIT
CORPS OF ENGINEERS, 200 N. COBB PARKWAY, BLDG 400 SUITE 404, MARIETTA, GA. 30062

WORK ORDER: 848e
REQUISITION: W33SJG32900192



COBBLES		GRAVEL		SAND			SILT OR CLAY		
		COARSE	FINE	COARSE	MEDIUM	FINE			
Sample No.	Depth (ft)	ASTM D2487 Classification			Nat w%	LL	PL	PI	Project MsCIP Barrier Island Restoration
B	4.5 to 8.8	Dark Greenish Gray, Poorly Graded Silty Sand (SP-SM), with a trace of gravel size shell.							
									Vibracore Sampling Pascagoula, MS
									Lab No. K5/3896
									Hole No. BI-PBS-128-13
GRADATION CURVES									Date 4/23/14

GRADATION CURVES