




DEPARTMENT OF THE ARMY, SAVANNAH DISTRICT, ENVIRONMENTAL AND MATERIALS UNIT
CORPS OF ENGINEERS, 200 N. COBB PARKWAY, BLDG 400 SUITE 404, MARIETTA, GA. 30062

WORK ORDER: 848e
REQUISITION: W33SJG32900192



COBBLES		GRAVEL		SAND			SILT OR CLAY			
		COARSE	FINE	COARSE	MEDIUM	FINE				
Sample No.	Depth (ft)	ASTM D2487 Classification			Nat w%	LL	PL	PI	Project	MsCIP Barrier Island Restoration
A	0.0 to 1.7	Dark Greenish Gray, Poorly Graded Silty Sand (SP-SM).								Vibracore Sampling Pascagoula, MS
									Lab No.	K5/4830
									Hole No.	BI-PBS-329-13
GRADATION CURVES									Date	4/23/14

GRADATION CURVES