




DEPARTMENT OF THE ARMY, SAVANNAH DISTRICT, ENVIRONMENTAL AND MATERIALS UNIT
CORPS OF ENGINEERS, 200 N. COBB PARKWAY, BLDG 400 SUITE 404, MARIETTA, GA. 30062

WORK ORDER: 848e
REQUISITION: W33SJG32900192



COBBLES		GRAVEL		SAND			SILT OR CLAY	
		COARSE	FINE	COARSE	MEDIUM	FINE		
Sample No.	Depth (ft)	ASTM D2487 Classification			Nat w%	LL	PL	PI
B	2.9 to 4.0	Dark Greenish Gray, Poorly Graded Silty Sand (SP-SM), with a trace of gravel size shell.						

Project	MsCIP Barrier Island Restoration
Vibracore Sampling	Pascagoula, MS
Lab No.	K5/4860
Hole No.	BI-PBS-380-13
Date	4/23/14

GRADATION CURVES