

DRILLING LOG		DIVISION		INSTALLATION		SHEET 1 OF 1	
1. PROJECT Gulf Shores, AL - Beach Restoration				10. SIZE AND TYPE OF BIT 4" VIBRACORE			
2. LOCATION (Coordinates or Station) X=1915984.300 Y=81021.200				11. DATUM FOR ELEVATION SHOWN (TBM or MSL) MLLW			
3. DRILLING AGENCY A.O.S./Olsen Associates, Inc.				12. MANUFACTURER'S DESIGNATION OF DRILL PNEUMATIC VIBRACORE			
4. HOLE NO. (As shown on drawing title and file number) C-25A				13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN disturbed: 2 undisturbed: 0			
5. NAME OF DRILLER C.Dill/E. Olsen				14. TOTAL NUMBER OF CORE BOXES 1			
6. DIRECTION OF HOLE <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED				15. ELEVATION GROUND WATER			
7. THICKNESS OF BURDEN 0 Ft.				16. DATE HOLE STARTED COMPLETED 11-26-99 11-26-99			
8. DEPTH DRILLED INTO ROCK 0 Ft.				17. ELEVATION TOP OF HOLE -28.2 Ft.			
9. TOTAL DEPTH OF HOLE 6.5 Ft.				18. TOTAL CORE RECOVERY FOR BORING 100 %			
				19. SIGNATURE OF G. ZARILLO, SEA,INC			
ELEV.	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	CORE REC %	UPPER SAMPLE NUMBER	REMARKS	
-28.2	.0					-28.2	0
			White fine sand. 10 YR 8/1 (SP)		0.5		
-31.0	2.8			100	3.0		2.5
			Light grey medium to fine sand. 10 YR 7/1 (SP)				
-32.5	4.3						
			Brownish-grey coarse shell and sand in mud matrix. 10 YR 5/2 (SW)				5
-33.6	5.4						
			Dark grey silty mud and small shell fragments. 10 YR 4/1 (ML)				
-34.7	6.5					-34.7	
							7.5
							10
							12.5
							15
							17.5
							20
							22.5
						Composite 0.0-4.0 ft.	