

DRILLING LOG		DIVISION		INSTALLATION		SHEET 1 OF 1	
1. PROJECT Gulf Shores, AL - Beach Restoration				10. SIZE AND TYPE OF BIT 4" VIBRACORE			
2. LOCATION (Coordinates or Station) X=1902497.700 Y=81513.800				11. DATUM FOR ELEVATION SHOWN (TBM or MSL) MLLW			
3. DRILLING AGENCY A.O.S.S./Olsen Associates, Inc.				12. MANUFACTURER'S DESIGNATION OF DRILL PNEUMATIC VIBRACORE			
4. HOLE NO. (As shown on drawing title and file number) C-46				13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN disturbed: 3 undisturbed: 0			
5. NAME OF DRILLER C.Dill/E. Olsen				14. TOTAL NUMBER OF CORE BOXES 1			
6. DIRECTION OF HOLE <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED				15. ELEVATION GROUND WATER			
7. THICKNESS OF BURDEN 0 Ft.				16. DATE HOLE STARTED COMPLETED 11-28-99 11-28-99			
8. DEPTH DRILLED INTO ROCK 0 Ft.				17. ELEVATION TOP OF HOLE -27.7 Ft.			
9. TOTAL DEPTH OF HOLE 10.4 Ft.				18. TOTAL CORE RECOVERY FOR BORING 100 %			
				19. SIGNATURE OF G. ZARILLO, SEA, INC			
ELEV.	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	CORE REC %	SAMPLE NUMBER	REMARKS	
-27.7	.0					-27.7	0
-28.8	1.1		Pale brown-light grey medium to fine sand, small shell fragments. 10 YR 8/1-8/2 (SP)		0.5		
			Light grey fine sand, small shell fragments. 10 YR 7/2 (SP)	100			2.5
					4.0	Large shell fragment, 3.8 ft.	
-32.9	5.2					-32.7	5
			Pale brown to very light grey fine sand, small shell fragments. 10 YR 6/2-7/1 (SP)				
-35.0	7.3			100	8.0		7.5
			White fine sand. 10 YR 8/1 (SP)				
-38.1	10.4					-38.1	10
							12.5
							15
							17.5
							20
						Composite 0.0-10.4 ft.	22.5

